## 限用物質含有情況標示聲明書 Declaration of the Presence Condition of the Restricted Substances Marking

證書號碼 / 受理編號:(No.) Certificate No/Application No.

商品標籤及商品檢驗標識:(Picture)

Product Label and Commodity Inspection Mark.

設備名稱: <mark>電源供應器</mark> ,型號(型式): <mark>S21A22L</mark> Equipment name Type designation (Type)							
單元Unit	限用物質及其化學符號 Restricted substances and its chemical symbols						
	鉛 Lead (Pb)	汞 Mercury (Hg)	鎘 Cadmium (Cd)	六價鉻 Hexavalent chromium (Cr+6)	多溴聯苯 Polybrominated biphenyls (PBB)	多溴二苯醚 Polybrominated diphenyl ethers (PBDE)	
電路板	$\bigcirc$	0	0	0	0	0	
塑膠外殼	$\bigcirc$	$\bigcirc$	$\bigcirc$	0	$\bigcirc$	$\bigcirc$	
金屬插頭刃片	$\bigcirc$	$\bigcirc$	$\bigcirc$	0	0	0	
電子零件 (高熔點溫度焊料 之含鉛量,電子元 件組件所使用玻 璃、陶瓷材料之含 鉛量)	_	0	0	0	0	0	
其它電子零件	$\bigcirc$	$\bigcirc$	$\bigcirc$	$\bigcirc$	$\bigcirc$	0	
USB 端子	0	0	0	0	$\bigcirc$	0	

|備考 1. "超出 0.1  $\mathrm{wt}$  %" 及 "超出 0.01  $\mathrm{wt}$  %" 係指限用物質之白分比含量超出白分比含量基準值

Note 1: "Exceeding 0.1 wt %" and "exceeding 0.01 wt %" indicate that the percentage content of the restricted substance exceeds the reference percentage value of presence condition.

備考 2. "〇"條指該項限用物質之百分比含量未超出百分比含量基準值。

Note 2: "O" indicates that the percentage content of the restricted substance does not exceed the percentage of reference value of presence.

備考 3. "一"係指該項限用物質為排除項目。

Note 3: The "-" indicates that the restricted substance corresponds to the exemption.

## 商品檢驗標識

 Commodity Inspection Mark	